

## 7. PROGRESS PHOTOS



Photo 1: Additional vertical support carried out below boundary wall of Cateco



Photo 2: Shuttering to reinforcement of retaining wall along GL A-AX' |1'



Photo 3: Casting of a section of staircase at GL G-H |2-3



Photo 4: Backfilling at water tank area



Photo 5: Shuttering to beam reinforcements along GL E-F|3



Photo 6: Casting of beam – GL G-H|5



Photo 7: Casting of column bases and strip footing of retaining wall along GL B-C|1-3



Photo 8: Formwork and reinforcement at retaining wall of staircase along GL B-C|1-2 and column at GL B-3 and GL C-3





Photo 9: Backfilling and compaction along GL Ax'-C'



Photo 10: Shuttering of Basement B1 floor slab



Photo 11: Reinforcement and conduits installation at soffit of Basement B1 floor slab



Photo 12: Casting of Basement B1 floor slab



Photo 13: Shuttering to reinforcement of column bases along GL B-C|5-6 and strip footing along GL Ax'-D|6



Photo 14: Shuttering to reinforcement at Lift Pit, columns and retaining wall along GL E'-J|7 at Basement B1



Photo 15: Deshuttering of column bases along GL B-C|2-3 and retaining wall along GL A'|1'-6



Photo 15: Backfilling and reinforcement to retaining wall at GL K'|1'-4