

FORM19: PROJECT PROGRESS REPORT

5.0 PHOTOGRAPHIC PROGRESS



*Picture 1: Removal of Vegetable Soil*



*Picture 2: Fixing of Hoarding to site*

FORM19: PROJECT PROGRESS REPORT



*Picture 3 & 4: Excavation Works and Carting Away*

FORM19: PROJECT PROGRESS REPORT



*Picture 5: Carting away of rocks*



*Picture 6: Setting out for underpinning works*