

7. PROGRESS PHOTOS



Photo 1: Selected fill & compaction below drain



Photo 2: Reinforcement, water bar and boxing to drain along GL E-J/7'



Photo 3: Drain along GL E-J/7'



Photo 4: Laying of tanking membrane to retaining wall along GL A-Ax/7'



Photo 5: Laying of spalls and crusher run to floor between GL A'-Ax/3-7'



Photo 6: Casting to column bases at GL F-H/1



Photo 7: Shuttering and reinforcement to columns



Photo 8: Reinforcement & Shuttering to 2nd lift retaining wall (below soffit of B2 slab) along GL F-J/7'



Photo 10: Selected fill & Compaction prior to laying of spalls