

## 7. PROGRESS PHOTOS



Photo 1: Knee bracing against Catéco wall



Photo 2: Backfilling across GL D-E /1-3'



Photo 3: Installation of tanking membrane along GL J/7



Photo 4: Formwork to stub columns and lift shaft along GL G-J /1-6



Photo 5: Installation of water bar at GL D-E /7



Photo 6: Casting of lift shaft and columns along GL F-H/3-6





Photo 7: Compaction of crusher along GL D-F/1'-7



Photo 8: Anti-termite treatment along GL D-F/1'-7



Photo 9: Reinforcement to Basement Floor B2 along GL D-F/1'-7 & GL F-K/1'-1



Photo 10: Casting of Basement Floor B2 along GL D-F/1'-7



Photo 11: Reinforcement and formwork to beam at soffit of Basement B1 along GL E-J/5



Photo 12: Casting of drain at cateco boundary.



Photo 12: Formwork to slab and side drain