

7. PROGRESS PHOTOS



Photo 1: De-shuttering of beams at GL Ax-D' | 1-6



Photo 2: Compaction of spalls at water tank area along GL J-Kx | 4-7



Photo 3: Shuttering to Basement B1 floor slab and beams along GL Ax-D' | 1-7



Photo 4: Casting of Basement B1 floor slab



Photo 5: Casting of Water Tank floor slab at Basement B1



Photo 6: Backfilling at GL Kx|1-4



Photo 7: Shuttering to Ramp 1 at GL A-Ax|1'-1



Photo 8: Shuttering to column reinforcement at GL C-D|5-6



Photo 9: Shuttering to reinforcement for wall at water tank along GL J-Kx|4-7



Photo 10: Shuttering to reinforcement at staircase 1 along GL G-H|2-3



Photo 11: Rendering of columns and beams at Basement B2 along GL K-Kx|2-4



Photo 12: Reinforcement to formwork and installation of conduits for Basement B1 slab



Photo 13: Application of protection to tanking membrane at GL D-F|7



Photo 14: Installation of penebar to water tank reinforcements



Photo 15: Installation of puddle flange at water tank