

## 7. PROGRESS PHOTOS



Photo 1: Shuttering to RC walls at water tank along GL J-Kx|4-7



Photo 2: Reinforcement, fixation of conduits and sleeves to slab along GL H-Kx|3-7



Photo 3: De-shuttering at water tank GL J-Kx|4-7



Photo 4: Making good and rendering at Basement B2 at GL H-Kx|2-4



Photo 5: Backfilling at ramp along GL A'



Photo 6: Shuttering to reinforcement at staircase along GL B-C|1-2



Photo 7: Casting of Basement B1 slab at GL H-Kx|1'-7



Photo 8: Casted Basement B1 slab/ Ground Floor



Photo 9: Backfilling along GL 7



Photo 10: Column reinforcement for column extension on Ground Floor GL D-F|7